

Cambridge Resources

WIRE CONNECTORS Model WCS-3H

To be sold only with installation instructions

Installation Instructions:

- 1. Turn off power before installing or removing connectors.
- 2. Strip wires 5/16" (7.9 mm). For #16 and smaller stranded wires, strip 3/8" (9.5 mm).
- 3. Pre-twisting unnecessary, hold stripped wires together with ends even. Lead stranded wires slightly.
- 4. Align any frayed strands or conductors.
- 5. Push wires into connector and screw on until two twists are visible in wires.

FOR USE WITH COPPER TO COPPER

Temperature Rating: 105°C (221°F) Max.

Voltage Rating: 600V Max. building wiring; 1000V Max. in fixtures and signs

Listed as a Pressure-Type Wire Connector on the following **Solid** and/or **Stranded** wire combinations:

2 #16 w/1 to 3 #22

1 #18 w/2 to 4 #20

1 #18 w/3 or 4 #22

1 #18 w/5 #22

2 #18 w/3 #22

1 or 2 #18 w/1 #20 w/1 #22

2 #18 w/1 or 2 #20 or #22

3 #18 w/1 #20 or #22

3 #18 w/2 #20 or #22

4 #18 w/1 #20 or #22 1 #20 w/4 #22

2 #20 w/2 or 3 #22

3 #20 w/1 or 2 #22 4 #20 w/1 #22

For UL Listed, CSA and CQC Certified

Voltage Rating 600V Max.:

1 #14 w/1 to 3 #20 or #22 2 #16 w/1 or 2 #20

Voltage Rating 300V Max.: 1 or 2 #14

3 #22 Sol w/2 #22 Str 3 #16 w/1 #18 1 #14 w/1 #16 w/1 #18 3 #16 w/1 or 2 #20 or #22 1 #14 w/2 #16 4 #16 w/1 #20 or #22

1 #14 w/2 #16 4 #16 w/1 #20 0 1 #14 w/3 #18 1 #18 w/1 #20

Warranty limited solely to repair or replacement; no warranty of merchantability, fitness for a particular purpose or consequential damages



MADE IN CHINA