

# Cambridge Resources

#### WIRE CONNECTORS Model WCS-2H

## To be sold only with installation instructions

Installation Instructions:

- 1. Turn off power before installing or removing connectors.
- Strip wires 7/16" (11.1 mm). For #16 and smaller wires, strip 1/2" (12.7 mm).
- Pre-twisting unnecessary, hold stripped wires together with ends even. Lead stranded wires slightly.
- 4. Align any frayed strands or conductors.
- 5. Push wires into connector and screw on until two twists are visible in wires.

### FOR USE WITH COPPER TO COPPER

Temperature Rating: 105°C (221°F) Max.

Voltage Rating: 600V Max. building wiring; 1000V Max. in fixtures and signs

Listed as a Pressure-Type Wire Connector on the following Solid and/or Stranded wire combinations:

## For UL Listed, CSA and CQC Certified

Voltage Rating 600V Max.:



Voltage Rating 300V Max.:

1 #12 w/1 #16 w/1 to 4 #22 1 #12 w/1 to 4 #20 2 #12 w/1 #14 w/2 or 3 #16 2 #12 w/2 #14 w/1 #16 2 #12 w/1 #16 w/4 #18 2 #12 w/6 #16 3 #12 w/1 #14 3 #12 w/1 #16 w/1 #20 1 #14 w/1 #18 w/4 #22 2 #14 w/1 #16 w/1 to 4 #20 2 #14 w/1 #16 w/1 to 4 #22 3 #14 w/1 #16 w/1 to 3 #18 1 #10 4 to 6 #16 1 #10 w/1 #12 w/3 or 4 #18 1 #10 w/1 #14 w/4 #18 1 #16 w/4 #18 2 #16 w/3 or 4 #18 3 #16 w/1 or 2 #20 w/1 to 3 #22 4 #16 w/1 #18 or #20 1 #10 w/1 #14 w/1 to 4 #20 1 #10 w/1 #14 w/1 to 4 #22 1 #10 w/1 or 2 #20 w/1 to 4 #22 1 #12 w/2 #14 w/3 #16 4, 5 or 6 #16 w/1 #22 1 #12 w/1 #16 w/1 to 4 #20 4 or 5 #16 w/2 #22

#### For CSA Certified

Voltage Rating 600V Max.:

1 #12 w/2 to 4 #16 or #18 2 #12 w/1 to 4 #14 2 #12 w/1 to 3 #16 or #18 3 #12 w/2 #14 3 #12 w/1 or 2 #16 or #18 4 #12 w/1 #16 2 to 4 #12 2 to 6 #14 3 to 9 #18 2 #14 w/1 to 4 #16 or #18 3 #14 w/1 to 3 #16 or #18 4 #14 w/1 or 2 #16 or #18 1 #10 w/1 to 2 #12 1 #10 w/1 to 4 #14 5 #14 w/1 #16 or #18 1 #12 w/1 to 5 #14

Warranty limited solely to repair or replacement; no warranty of merchantability, fitness for a particular purpose or consequential damages



MADE IN CHINA